

REINFORCED STABILISER LINK (N66-80170)

MARKET-REPORTED ISSUE

- Fracture or cracking reported
- Failures occur at known high-stress points (the weld junction)
- Risk increases with mileage, load, and road conditions
- Repeated cyclic loading causes fatigue cracks

THE NAKATA SOLUTION

- Reinforced weld support at the stabiliser link arm junction

ADVANTAGES

- Increased structural strength at the highest stress point
- Improved resistance to vibration and torsional loads
- Reduced risk of weld fatigue
- Extended component service life
- Maintains proper anti-roll bar performance

APPLICATIONS

Front axle left / right:

- BMW 3 Series (90-00)
- BMW Z1 (88-91)
- BMW Z3 (95-03)

INSTALLATION NOTE

- Replace stabiliser links in pairs and tighten fasteners to manufacturer specifications



CONTACT

01302 727 312
info@nakata.uk

CONNECT

[in](#) [ig](#) [fb](#) /nakatauk
nakata.uk

NAKATA®
COUNT ON US